

Photographs to Accompany the Access Audit of Wadham College

July 2021

Photo 1: Wicket Door



Photo 2: Lodge desk – Signage



Photo 3: Alarm cords tied up



Photo 4: Reset Button Height




Photo 5: Reset Button and Flush



Photo 6: Flush Non – Transfer Side




Photo 7: Bowra Fittings / Bin




Photo 8: MCR Fittings / Bin




Photo 9: Towel dispenser opposite sink Photo 10: Toilet roll behind seat



Photo 11: Staircase IV nosings



Photo 12: Staircase 25 nosings



Photo 13: External steps Bowra




Photo 14: External steps Barbara Naylor Garden




Photo 15 : Staircase XI effective nosings



Photo 16 Merifield effective nosings




Photo 17: Staircase 2 – one bannister



Photo 18: Staircase 6 Bannister



Photo 19: Staircase 26 – One handrail



Photo 20: Staircase 32 one bannister



Photo 21: Handrails visual contrast



Photo 22: Overgrowing vegetation




Photo 23: Back Quad - drainage channel/lawn edge




Photo 24: Step requiring ramp



Photo 25: JCR Bar High furniture



Photo 26: Bar Graduate Centre



Photo 27: Visual contrast



Photo 28: Bins in Knee recess




Photo 29: Alarm Cord



Photo 30: Flush Dr Lee Shau Kee




Photo 31: Alarm Cords Dr Lee Shau Kee




Photo 32: Staircase Six Alarm Cord




Photo 33: Oven base DWB



Photo 34: Fridge Freezer Handles



Photo 35: Portable step Merifield



Photo 36: Slope Merifield Block D

